

Photograph C-1: TAAF Building 1235 (Black Powder Igloo) currently being used by the Nye County Hospital to store files and records.



Photograph C-2: Interior of TAAF Building 1235 (Black Powder Igloo) view of files and records of Nye County Hospital being stored inside.



Photograph C-3: TAAF Building 1250 (Strategic Storage Igloo) currently being used by the Nye County Sheriffs Office for storage.



Photograph C-4: Interior of Building 1250 (Strategic Storage Igloo).



Photograph C-5: TAAF Building 1255 (Warehousing Igloo) currently being used by Nye County Building and Grounds for storage.



Photograph C-6: Interior of Building 1255 (Warehousing Igloo).



Photograph C-7: Three unidentified 55-gallon drums outside Building 1255 (Warehousing Igloo).



Photograph C-8: Suspect asbestos-containing tiles scattered on the ground at Building 1230 (AC Magazine).



Photograph C-9: TAAF Building 1380 (hangar). Note the UST vent pipe remaining at the southwest corner of the building.



Photograph C-10: Waste oil drum outside Building 1380 (hangar). Note the soil staining along the drum.



Photograph C-11: View of old oil cans, battery, and stained soil near Building 1380 (hangar).



Photograph C-12: TAAF Building 1710 (hangar) burned down in 1986.



Photograph C-13: ACFS-Midway Street view of remaining fuel islands with fuel system piping.



Photograph C-14: Oil/water sump located at the ACFS-Midway Street fuel island.



Photograph C-15: ACFS-inside taxiway. View of remaining fuel islands with fuel system piping.



Photograph C-16: ACFS-Taxiway 4, view of remaining fuel islands with fuel system piping.




Photograph C-17: View of transmix holding tank at oil refinery property.



Photograph C-18: View of oil stained soil at oil sludge dumping area from the oil refinery operations being placed on top of a former TAAF building slab foundation.



Photograph C-19: View of gravel-filled drain excavated through the former concrete slab of hangar Building 1600 used by the oil refinery for surface runoff drainage.



Photograph C-20: View of aboveground storage tanks that store fuel for the Desert Flying Service.